## भारत सरकार GOVERNMENT OF INDIA रेल मंत्रालय MINISTRY OF RAILWAYS (रेलवे बोर्ड RAILWAY BOARD)

No. 2009/M(C)/141/6 Vol.III (Pt.)

New Delhi, dated: 78.09.2018

Principal Chief Mechanical Engineer, All Zonal Railways All Production units

> Sub: Accident in 12215 Up Delhi Sarai Rohilla – Bandra Terminus Garib Rath Express Train at Ajmer Railway Station in Nonelectrified BG Section of Ajmer Division of North Western Railway at about 16.35 hours on 26.03.2018

> Ref: CRS/Western Circle letter No.T.16020/2/17-18/WC/265/75 dated 20.04.2018

In reference to above subject accident, CRS / Western Circle vide item No. 7.1 of preliminary report had recommended as under

"Removal of Aluminium Chequered Plates from door way area and provision of PVC Sheet in front of electrical equipment and panels on all coaches running on Indian Railways".

The above recommendation of CRS was examined at Railway Board and following has been approved by AM/ME  $\leftarrow$ 

- Chequered plates may be removed from the doorway area of coaches that have provision of Mini Pantry equipment.
- 2. For balance coaches railway will continue with Chequered plates till a suitable abrasion resistant solution in lieu of Chequered plates is found.

May please ensure compliance.

(Navaid Talib)

Director Mech. Engg/(Chg)

Railway Board

Copy:

Dir/Safety-III/Railway Board